

Oil Field Environmental Incident Summary

Incident: 20140915084548 **Date/Time of Notice:** 09/15/2014 08:45

Responsible Party: Rud Transportation

Well Operator: OXY USA INC.

Well Name: HENRY GURKE 1-30-19H-141-96

Field Name: ST. ANTHONY

Well File #: 23928

Date Incident: 9/14/2014 **Time Incident:** 02:00

Facility ID Number:

County: DUNN

Twp: 141

Rng: 96

Sec: 30

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
1141 Jerry Lane
Dickinson , ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.8 Mile

Distance Nearest Water Well: 0.8 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	0.3	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Contaminated surface material on well pad.

Areal Extent:

Potential Environmental Impacts:

Contaminated surface material on well pad.

Action Taken or Planned:

Rud driver immediately recovered the standing liquids, the remaining contaminated materials will be recovered and disposed of at the completion of the frac.

Wastes Disposal Location: TBD

Agencies Involved:

Updates

Date: 9/15/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location according to the report. NDIC retains oversight.